

## **Dock Committee Report, June 2025**

The state of the docks is fairly good... there are a few boards that need replaced now and some of the fingers between slips will need replaced in the near future. The worst area is between Lewis/ Maning slips .. also the upper section above the floating docks has several weathered boards that could be replaced but not a heavily used area., that could wait for another year or until new docks done !

When appropriate we can get bids and do sections at a time if we do not move forward on new docks .

One or two of the navigational markers have broken seals and will need replaced .

The floating docks weather the winter well with only one of the baskets needing some minor repairs . Art was able to weld it

Recommending budget be set aside for one or two navigational markers and replacing boards!